



# READ ME FIRST!!!

This AN8103 RF Amplifier was repaired and fully calibrated in accordance with OEM published documentation. Adjustments may be required as a result of differences in exciter output in the field.

OEM service instructions can be located at the GE Healthcare Customer Documentation Portal. Installation/alignment verification instructions are contained within the service documentation and must be adhered to for correct operation of the RF amplifier.

Portal link: <https://customer-doc.cloud.gehealthcare.com/#/cdp/dashboard>



Failure to follow these instructions will result in incorrect RF amplifier operation resulting in system errors or poor image quality.

**This part has tamper-proofing in place. If part has been tampered with, without prior authorization, the part will be treated as an exchange and credit will not be issued.**

*This document is uncontrolled – for information purposes only.*